

OFFICE ROOF

Existing coating was applied in 2007 10 Mils
DFT SUPERTHERM ® over HLM 5000 no maintenance has been performed since.

(no clean up of debris on the roof)

July 2012 Roof Maintenance

First we cleaned the surface of the roof to a clean, dry and sound condition ready to accept a new coating system.







An additional 8 mils WFT = 5 mils DFT of <u>SUPERTHERM</u> ® was added over the whole roof.







Eagle Specialized Coatings And Protected Environments | a Division of DW PEARCE Enterprises Ltd. (1979) Tel: (604) 576-2212 • Email: info@eaglecoatings.com • Web: www.eaglecoatings.com





Pre Striped then applied first coat of SP LIQUID
MEMBRANE ® at 8 mils WFT







applied Second Coat cross hatched of <u>SP LIQUID</u>

<u>MEMBRANE</u> ® at 6 mils WFT for a total of 14 mils WFT = 6 mils

DFT





