


## **CHELSEA GARDENS**

## 1998

**RUST GRIP** ® top coated with **ENAMO GRIP** ®











This metal arch was being attacked by the chlorine in the swimming pool below. The Epoxy coating had completely failed after about 2 years. In 1998 we encapsulated the metal first with <u>RUST GRIP</u> ® and then top coated with 2 coats crosshatched of <u>ENAMO GRIP</u> ®This picture was taken in 2000 on our two year follow up. In 2010 the coating system still looks like new.